



THE RESORT & CLUB
AT LITTLE HARBOR
A Caribbean-Style Island Resort on Tampa Bay

To whom it may concern:

On October 28, 2008 we had a severe water intrusion effecting 5 condominiums and 2 corridors in the Harborside Condominium, a five story building. The Engineering Department requested that the Housekeeping Department call DriRite (a structural drying and microbial remediation) and within one hour the crews started to arrive. Chris Nethercutt and his crew worked well into the evening removing water from each unit and setting up drying equipment. The next morning they returned and for the next 12 days Tim Campbell monitored the drying process using the very latest equipment.

I cannot say enough good things about DriRite and would definitely use them again. I highly recommend this company to anyone who might be in need of this type of service.

Sincerely,

Mark Lazarto
Maintenance Superintendent
The Resort & Club at Little Harbor

The Resort & Club at Little Harbor
611 Destiny Drive
Ruskin, FL 33570
813-645-3291
www.staylittleharbor.com